

Tel: 966 12 684 8046  
 966 12 684 8959  
 Fax: 966 12 640 5622  
 AFS OEJDYKYX  
<http://www.sans.com.sa>  
 E-mail: [aim@sans.com.sa](mailto:aim@sans.com.sa)

**KINGDOM OF SAUDI ARABIA**  
 GENERAL AUTHORITY OF CIVIL AVIATION  
 SAUDI AIR NAVIGATION SERVICES  
 AERONAUTICAL INFORMATION MANAGEMENT  
 P. O. BOX 929, JEDDAH - 21421

**AIP  
 SUP  
 AIP SUP 44/25  
 12 NOV 2025**

## OEJN - JEDDAH / KING ABDULAZIZ INTL AIRPORT - Repainting project for Apron 6

### 1 .Introduction:

The purpose of this AIP Supplement is to notify aircraft operators regarding the new project of repainting apron 6, which will involve implementing new approved design for the whole apron. The project will be broken down into three phases.

### 2 .Timeframe for the installation activities:

The period of the implementation activities of the repainting and implementing new design on apron 6. These activities are divided as follows:

Project Phases	Activity	Duration	Consequence	Remark
Phase 1	Portion of TWY E between TWY R and Stand 6-7 Closed	+ 8 week	• Each phase will be activated by NOTAM.	-
Phase 2	Portion of TWY E between Stand 6-4 to North End Closed	+ 8 week		
Phase 3	Portion TWY F between TWY GA to North End Closed	+ 8 week		

### 3 .Apron redesign phases:

#### Phase 1

- The existing markings for stands 6-1, 6-2, 6-3, 6-4, 6-5, 6-11, 6-12, 6-13, and 6-14 will be fully removed. A new stand marking layout will be implemented for stands 6-1 through 6-5.
- Aircraft movements for stands 6-15 to 6-26 will enter and exit via Taxiway F.
- Similarly, aircraft movements for stands 6-7 to 6-10 will also use Taxiway F for entry and exit.
- Stand 6-6 will be closed to mitigate the Jet Blast issue.

#### Phase 2

- The existing markings for stands 6-6, 6-7, 6-8, 6-9, and 6-10 will be completely removed. A new stand marking layout will be implemented. The final configuration for Phase 2 will consist of five stands — 6-6, 6-7, 6-8, 6-9, and 6-10.
- Aircraft movements at stands 6-15 to 6-26 will enter and exit via Taxiway F.
- Aircraft movements at stands 6-1 to 6-4 will enter and exit via Taxiway E.
- Stand 6-5 will be closed to mitigate the Jet Blast issue.

#### Phase 3

- The existing markings for stands 6-15 through 6-26 will be completely removed. A new stand marking layout will be implemented. The final configuration for Phase Three will consist of twelve stands — 6-11, 6-12, 6-13, 6-14, 6-15, 6-16, 6-17, 6-18, 6-19, 6-20, 6-21, and 6-22.
- Aircraft movements at stands 6-1 to 6-10 will enter and exit via Taxiway E

**4 .Inquiries:**

For any inquiries, please contact:

Aerodrome / SANS	CONTACT DETAILS
Jeddah TWR	Name: JED Tower Email: <a href="mailto:jedtwr@sans.com.sa">jedtwr@sans.com.sa</a>
Aerodrome Operator (JEDCO)	Name: Adil Abdo Email: <a href="mailto:aabdo@jeddahairports.sa">aabdo@jeddahairports.sa</a>
Aerodrome Operator (JEDCO)	Name: Moataz Faraj Email: <a href="mailto:mafaraj@jeddahairports.sa">mafaraj@jeddahairports.sa</a>

-END-

